



**GENERAL PARENTS-TEACHERS ASSOCIATION (GPTA)  
SY 2025-2026**

**ACCOMPLISHMENT REPORT: REPAIR OF THE SCHOOL ENTRANCE CANOPY**

**I. RATIONALE**

The repair of the school entrance canopy was undertaken to address safety and convenience concerns for both learners and visitors. Over time, the roofing materials had significantly deteriorated due to age and exposure to varying weather conditions. The old roofing caused frequent leaks whenever it rained, resulting in dripping water that posed discomfort and possible hazards at the school entrance. By repairing the canopy, the GPTA ensures a safer and more welcoming environment for everyone entering the school. The project also supports the preservation of school facilities, preventing further damage that could lead to higher repair costs in the future. Overall, the repair was a necessary step in maintaining a functional and presentable entrance that reflects the GPTA officers' commitment to safety and convenience.

**II. OBJECTIVES**

The repair of the school entrance canopy was done to:

- to ensure the safety and comfort of learners, teachers, and visitors by eliminating leaks and preventing potential hazards caused by dripping water.
- to preserve and maintain the school's infrastructure by replacing the old and deteriorated roofing materials of the entrance canopy.
- to provide a clean, orderly, and welcoming school environment that supports the school's commitment to quality service and care for its stakeholders.

**III. NARRATIVE ACCOMPLISHMENT REPORT**

The repair of the school entrance canopy was successfully carried out on September 11, 2025, through the collaborative efforts of the GPTA officers along with some school/church workers. Their teamwork and cooperation ensured that the project was completed efficiently and within the same day. Work began at around 8:00 AM and was completed by 1:00 PM. The focus of the repair was to replace the old and dilapidated plastic roofing, which had become worn out over time and caused water drips whenever it rained. A total of eight new plastic roofing sheets were installed, ensuring a sturdier and more reliable cover for the school entrance. The materials used were of better quality, making the canopy more durable against future weather conditions. The total cost of the project amounted to ₱3,140, which covered all expenses for the roofing materials. This amount was generously donated by the GPTA President, Mr. Arniel Campos. The GPTA officers also extended their contribution by donating lunch and snacks to those who worked during the repair. With the new



canopy roofing in place, the entrance area is now safer and more comfortable for learners, teachers, and visitors. Truly, the project stands as a testament to the GPTA officers' commitment and dedication in creating a better, safer, and more conducive learning environment for all.

#### **IV: ATTACHMENTS**

- a. Photos (before, during, and after installation)
- b. Receipt of material cost
- c. Attendance

Prepared by:

SAULA T. MAYOCYOC  
GPTA Secretary

Approved by:

ARNIEL A. CAMPOS  
GPTA President

Noted by:

CARLOS B. LA-US  
OIC, Office of the Principal



# EPIPHANY CHRISTIAN ACADEMY OF LA TRINIDAD, INC.

La Trinidad, Benguet

IB-02 Epiphany Compound  
Betag, Km.5, La Trinidad, Benguet

Principal's Office: (074) 309-6664



Before: The roof of the school entrance canopy shows signs of deterioration, including visible damage from age and weather exposure.



During: The repair work on the school entrance canopy roof was in progress, with old materials being replaced to restore its durability. September 11, 2025.



# EPIPHANY CHRISTIAN ACADEMY OF LA TRINIDAD, INC.

La Trinidad, Benguet

IB-02 Epiphany Compound  
Betag, Km.5, La Trinidad, Benguet

Principal's Office: (074) 309-6664



After: The roof of the school entrance canopy has been fully repaired, with new plastic roofing installed. September 11, 2025.

